King County International Airport

ARFF Incident Reports

2009

Fuel Spills/Fueling Violations

Incident Type: Fuel Incident		Date Occurred: 01/15/2009	Date Repo	orted: 01/15/	2009			
Incident D	escription: Fuel Spill at Galvin's	Time Occurred: 0115	Time Rep	orted: 0130				
Business N	ame: Galvin's Executive Ramp							
Business A	ddress:							
Reporting	Party: Galvin's							
Reporting	Party Address/Telephone:							
Narrative: While a Bombardier Challenger was being refueled, four to five gallons of Jet-A fuel leaked from the aircraft onto the ramp. The Gavin's crew stopped the fuel flow and immediately began efforts to clean the spill. After a few minutes, Airport Operations was notified first and then the ARFF station. Fire Command (Sgt. Davis) and FR2 (McClure and Proffitt) responded to the location. Upon arrival, there were four of the Galvin's crew working to clean it up with absorbant material. None of the fuel went into the nearby drain. FR2 maintained a standby for firewatch during the cleanup. Follow up interviews were done. It was determined that the leak came from the left wing vent. The pilot said that the spill was due to overfilling. Overall, ARFF spent approximately 20 minutes at the site and used no materials during the clean up aftermath. Department of Ecology was notified of the incident. An airport management page went out as well. Interviewed: James Anderson, Galvin's Supervisor Tom Drengacz, Pilot / Jet Solutions LLC / phone 972-720-2771 Aircraft: Bombardier Challenger (CL-600-2B16) / mfr year 2007 / fixed wing / multi-engine / serial 5719 / N339FX / Reg Owner: Bombardier Aerospace Corp DBA / Dallas, Texas /								
R/O (1):	Davis, D. 10618	Signature: Notificat		Notified	E-Mail			
		BFI ATO	CT	\boxtimes				
R/O (2):	McClure, B. 07260	KCIA C	hief	\boxtimes	\boxtimes			
R/O (3):	Proffitt, P. 06250	KCIA M	gmt	\boxtimes	\boxtimes			
R/O (4):		KCIA M	aint	\boxtimes	\boxtimes			
Supervisor	: Davis, D. 10618	visor Review:						
Action/Other notifications: Cost recovery information: FR2 (Oshkosh 1500) spent 20 minutes on site. Three ARFF deputies spent 20 minutes on site as well. No ARFF materials were expended during the clean-up efforts.								

Incident Type: Fuel Incident		Date Occurred	Date Occurred: 02/12/09 Date R		eported: 02/12/09		
Incident Description: Die	Time Occurred	Time Occurred: 1540 Time Reported: 1550					
Business Name: IAS (wor	king for DHL)						
Business Address:							
Reporting Party: Decoteau	ı, Dave						
Reporting Party Address/	Telephone: 296-7334						
Narrative: At 1540 Decoteau, from airport Opts., notified ARFF that that he was told by an IAS employee that there was a small diesel spill at the DHL ramp. ARFF responded with Deputies Wills and lange in FR1. On their arrival they met Decoteau and discovered the spill was approximately 1/2 quart of diesel from one of the DHL loaders. It was in the process of being cleaned up. FR1 stood down and returned to base. Time out of service 20 minutes with no ARFF supplies used. Page sent.							
R/O (1): McClure, B. 0	7260	Signature:	Notifica BFI AT	tion(s)	Notified	E-Mail	
R/O (2): Wills, K.T.D. 01853			KCIA (Chief			
R/O (3): Lange, K. 08975			KCIA N	KCIA Mgmt			
R/O (4):			KCIA N	Aaint			
Supervisor:	Su	pervisor Review:					
Caballero	Fukuda M	[atheson	Olmstead		Updyke		
Davis		IcClung	Proffitt		Vanderwal		
DeFries		IcClure		Stephens Wills, K_			
Grout	Masters						
Action/Other notification	ons:				<u> </u>		

Incident Type: Fuel Incident	Date Occurred: 02-14-2009	Date Repor	rted: 02-14-2009				
Incident Description: Fueling Violation	Time Occurred: 1512 hrs	Time Repor	r ted: 1512 hrs				
Business Name: Galvin's Flying Service							
Business Address:							
Reporting Party:							
Reporting Party Address/Telephone:							
Narrative: While performing an airport inspection with Tammi Schreier (Airport Ops), we noticed a man napping while refueling a truck at the NE fuel farm. The man was in the driver's seat of his fuel truck and had his head in one hand while the other was wrapped around his body for warmth. As I approached the driver's cab, the driver awoke. I asked where the refueling switch was and he stated that it was under his leg. The truck was grounded properly. The driver presented identification upon request and I told him this was a reportable event. The driver, Stephen McKillop, knew that it was wrong and did not protest the issue. I took his information and told him that an administrative action could result. McKillop understood. McKillop was refueling a Galvin's truck with jet A when the incident occurred. I researched the the King County Code and determined that McKillop's conduct violated KCC 15.40.010 (General Safety/Fueling and Fuel Storage). I did not cite him. I listed McKillop's information below. Stephen McKillop / Galvin's Flying Service / phone: 206-763-0353 / red badge exp: 10-31-2009							
R/O (1): Davis, D. 10618	Signature: Notificat	tion(s) N	Notified E-Mail				
R/O (2):	KCIA C	hief					
R/O (3):		Igmt					
R/O (4):	KCIA M	laint					
Supervisor: Davis, D. 10618	visor Review:						
Action/Other notifications:							

Incident Type: Fuel Incident		Date Occurred: 02-18-2009	Date Reported: 02-18-2009		
Incident Description:	Fuel Spill at Guardian One	Time Occurred: 1545	Time Reported: 1545		
Business Name:	King County Sheriff's Office				
Business Address:	Air Support Unit / Guardian One Hangar				
Reporting Party:	Adam Speck / Airport Maintenence				
Reporting Party Address/Telephone:					

Narrative: While driving by, Adam Speck noted a fuel truck leaking a small amount of fuel near the Guardian One hangar. It was reported to Dave Decoteau of Airport Operations and then relayed to ARFF.

ARFF responded with FR1 (Wills, Stephens) and with PU65 (Davis). The truck was located approximately 200 feet west of the Guardian One hangar and had a spill of about two feet in diameter directly underneath it. The truck had jet A tags on it and had an extension cord attached to it (for engine starts) that ran from the hangar.

Minutes after ARFF's arrival, Guardian One pilots (O'Neal, Potter, and Houck) arrived and they were informed of the problem. An absorbent pad was placed underneath the fuel truck. The truck tank was empty of jet A fuel, however, there was enough residual to leak through a swivel joint on the hose reel.

Later, Deputy Kirk Wills, ARFF fire inspector, followed up and "red tagged" the vehicle as unsafe. The truck is a 1976 International, military green color, license plate 34888C.

Time spent at the incident was approximately 20 minutes. No spill or clean up materials were used by ARFF or Airport Ops.

R/O (1):	Davis, D. 10618	Signature:	Notification(s)	Notified	E-Mail
			BFI ATCT	\boxtimes	
R/O (2):	Wills, K.T.D. 01853		KCIA Chief	\boxtimes	\boxtimes
R/O (3):	Stephens, W 16332		KCIA Mgmt	\boxtimes	\boxtimes
R/O (4):			KCIA Maint	\boxtimes	\boxtimes
Supervisor	: Davis, D. 10618	Supervisor Review:			

Action/Other notifications: